

03500.015868



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

YOSHIYUKI ENDO

Appl. No.: 09/976,093

Filed: October 15, 2001

For: EXTERNAL STORAGE DEVICE FOR
IMAGE PICKUP APPARATUS, CONTROL
METHOD THEREFOR, IMAGE PICKUP
APPARATUS AND CONTROL METHOD
THEREFOR

U.S. Patent No.: 6,965,403 B2

Issued: November 15, 2005

Examiner: Aung Moe

Group Art Unit: 2612

March 9, 2006

Certificate
MAR 13 2006
of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

03/10/2006 JADD01 00000105 6965403

01 FC:1811

100.00 OP


It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

MAR 14 2006

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentee's undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Lawrence A. Stahl
Attorney for Patentee
Registration No. 30,110

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

LAS:eyw

MAR 14 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,965,403 B2

DATED : November 15, 2005

INVENTOR(S) : YOSHIYUKI ENDO

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER PAGE AT ITEM [30]:

Foreign Application Priority Data, "2000/314709" should read --2000-314709--; and
"2001/316192" should read --2001-316192--.

COLUMN 1:

Line 49, "once" should read --first--.

COLUMN 2:

Line 46, "once" should read --first--.

COLUMN 7:

Line 33, "i for" should read --for--.

COLUMN 10:

Line 50, "input/outoput" should read --input/output--.

Line 54, "hanged" should read --changed--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,965,403 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

LAS:eyw DC_Main 233512v1



MAR 14 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,965,403 B2

DATED : November 15, 2005

INVENTOR(S) : YOSHIYUKI ENDO

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER PAGE AT ITEM [30]:

Foreign Application Priority Data, "2000/314709" should read --2000-314709--; and
"2001/316192" should read --2001-316192--.

COLUMN 1:

Line 49, "once" should read --first--.

COLUMN 2:

Line 46, "once" should read --first--.

COLUMN 7:

Line 33, "i for" should read --for--.

COLUMN 10:

Line 50, "input/outoput" should read --input/output--.

Line 54, "hanged" should read --changed--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,965,403 B2

No. of add'l. copies
@ 30¢ per page



2006